



Legislation Details (With Text)

File #: 15-1481 **Version:** 1 **Name:**

Type: Application **Status:** Agenda Ready

File created: 3/27/2017 **In control:** Historical Architectural Review Board

On agenda: 4/3/2017 **Final action:**

Enactment date: **Enactment #:**

Title: 3. Case Number HDC 2017-00005 Address: 433 ½ N. Howard Street
Proposal: remove aluminum siding; remove paint from brick; repair, replace, repoint brick as needed; replace windows, currently 1 over 1 vinyl, owner requests 2 over 2 wood aluminum clad; replace front entry door; remove aluminum siding from dormer, repair and paint; replace porch light; make door awning historically appropriate; remove siding, install slate shingle roof; install historical iron grate on coal window; paint trim.

Sponsors:

Indexes:

Code sections:

Attachments:

Date	Ver.	Action By	Action	Result
------	------	-----------	--------	--------

3. Case Number HDC 2017-00005 Address: 433 ½ N. Howard Street
Proposal: remove aluminum siding; remove paint from brick; repair, replace, repoint brick as needed; replace windows, currently 1 over 1 vinyl, owner requests 2 over 2 wood aluminum clad; replace front entry door; remove aluminum siding from dormer, repair and paint; replace porch light; make door awning historically appropriate; remove siding, install slate shingle roof; install historical iron grate on coal window; paint trim.